

Inspection of Sewers.

Apr. 3. 1891.

Entered Manhole Cor. Wash. Ave
and 24th St.

In good condition only
at 10" inflow from South.

It should be made smoother
on bottom.

Enter M. Hole Bet 23+24 on Wash,
Light - cor. Wash + 24. Light
not visible, only dead water
in Sewer.

M. Hole fairly well
plastered,

Enter M. hole Cor Wash +
23d. Light - $\frac{1}{2}$ Bet South
Light - visible o.k.

$\frac{1}{2}$ " water flowing in from South
Tide only west.

M. hole o.k.

Enter M. hole bet. Wash +
Grant on 23,

Light - at Wash + 23 visible
Water 1" deep slow current.

M. hole in fair shape.
Tide dripping.