

Enter M. hole cor. 23d +
Grant.

Cannot see light $\frac{1}{2}$ blk
east. Water 3" deep slow current
M. hole in nice shape —
well plastered up.

Send light $\frac{1}{2}$ blk south.
Plainly visible. $\frac{1}{2}$ " water
coming in from south. Both
tiles dry.

In main sewer (E+W)
sand $\frac{3}{4}$ " deep.

Enter M. hole 23d Bet Grant
+ Lincoln

Cannot see light $\frac{1}{2}$ blk east.
Man hole in good shape
Water 5" deep.

Tile running very little.

Enter M. hole cor. Lincoln
+ 23. Cannot see light
 $\frac{1}{2}$ blk east.

Water 5" deep, - moderate
current.

Man hole well plastered
 $\frac{1}{2}$ " sand in sewer.

Send light $\frac{1}{2}$ blk south
Light plainly visible
 $\frac{1}{8}$ " stream from south.

Tiles just wet.