

Enter Manhole 22^d St and Grant.

Plastered moderately - not very good
Tile from East flowing very small stream
Light at Manhole Lincoln Ave bet
22^d and 23^d St visible.

Water from East 4 1/2" - Moderately swift current

Water from South 1/2" deep swift current
Tile from South flowing small stream
Some point East of Manhole large stream
of water entering.

Must be repaired before accepting

Light at Manhole 22^d St bet
Grant and Washington visible.

Enter Manhole 22^d St bet
Grant and Washington.

Light at Manhole 22^d St & Washington
is not visible.

Bottom Well plastered
Can hear the roar of water to the west
distinctly.

Break in sewer pipe probably about 1/2 the
way bet Grant & Washington

Tile from East running a small stream
Water in sewer 2 1/2" deep - Current Moderate.