

Enter Man hole Washington Ave bet  
22<sup>d</sup> and 23<sup>d</sup> Sts.

Man hole bottom well plastered.  
File from South dripping.  
Light at Flush Tank 23<sup>d</sup> and Washington  
Ave not visible.  
1 1/2" Water running very slow.

---

Enter Man hole 22<sup>d</sup> + Washington  
Man hole bottom well plastered.  
Water 1 1/2 in deep.

File running small stream.  
Light at Man hole Wash<sup>n</sup> Ave bet  
22<sup>d</sup> + 23<sup>d</sup> St is visible.

---

Inspection of Sewers,  
Apr. 7, 1891.

37

Enter man hole Cor 26<sup>th</sup> + Washington.  
Needs repairing bottom + part of sides  
near bottom as water is coming through  
pavement. Short distance north of  
man hole large stream of water  
entering pipe, - makes quite a noise.

---

Enter Man hole, Wash, bet 25 + 26  
Light - S. 1/2 Bell visible.  
Water 2 1/2 in deep.

Small stream seeping from east  
must be tightened up.  
Bottom all right,