

Enter M. hole Cor. 25th + Wash.
Light 1/2 Blk counts not visible

Bottom well paved.

Leak from west. - must be
fixed. Water swift. 3" deep.

Tide flowing moderate stream.

Enter M. hole Wash, lot 24 + 25
Light 1/2 Blk counts visible

Leak from east to be stopped
Tide just dropping

Bottom well plastered
Water swift 3" deep.

Enter M. hole 24th + Wash.
Light 1/2 Blk counts visible

Well plastered

Tide only water.

Water from south 2" very swift,
water down street grade.

When water gone west 2 1/2" deep.

Enter M. hole 24th Bet Wash +
Grant, Light 1/2 Blk. east visible,

Well plastered

Water smooth current
and 3" deep.