

Inspection of Sewer Pipe Lines
by Horton - April 17th - 91

Manhole at 26th + Washington Ave.

About 1" deposit of cement not set
in bottom. Can hear noise of water
entering few feet to the North.

About 1/2" water (the seepage into man-
hole) entering pipe.

Manhole bet 26th + 25th on Washington Ave

Well Plastered. 2" Inches of Water.
Small Current. Tile from South flange size
of pencil. About same amount of water
(size of pencil) coming in from East through
hole in plaster about the pipe.

Manhole 25th St + Washington Ave ¹⁴⁹
Fairly well plastered. 3" of Water.
Tile running 3/4" Water from South.
Soak of 1/2" water on E. side of pipe ✓
near top of pipe entering from West.
Also leak from West at South
end of Manhole - Stream about 1" di-
ameter entering.

Manhole bet 25th and 24th West Ave

Well plastered 2 1/2" Water.
Tile just dripping. No leaks.