

Center Manhole on 23^d between
Lincoln and Wall
Manhole in good condition
on soft bricks about (1 1/2") one and
one half inches of sand in
bottom of sewer. Needs flushing badly
No leaks to be seen
lights passed 1/2 half way through
to manhole on Wall, level.

23^d and Wall 2nd
Manhole in good condition
Outlet of sewer on 23^d St cement worn
off. Bricks cutting badly.
South end of Bricks sewer in this
Manhole Bricks seem all right
in North end few soft Bricks
about (4") four inches above
presently water line

Sept 29th 1891 ^{4th} ⁵¹
Center Manhole 23^d St. ^{front}
and Lincoln.

Manhole in good condition
no difference in bricks good sized
stream running best.
No leaks to be seen.

23^d and Lincoln 2nd
Manhole in good condition small water
in east side
No difference in bricks.
good stream of water passing
through sewer. Small stream
running into sewer from South
No leaks to be seen in sewer