

Wall ave 25th St. North Property

No hole dist. Paces Remarks

#1 15-

#2 ✓
2

84 pipe exposed for
joint caused, by Leo Shipley, pipe

#3 3 130 pipe exposed for 6 ft
Leo Shipley, pipe cupped 1/8 deep, sandy clay

#4 4 174 This hole 7 ft long

two places about 1/4 in in Diam Rust

#5 5 206 This hole 7 ft long pipe
numerous small rust pits in

#6 6 258 This hole 4 ft long

Iron, joint-exposed, slight leak,

#7 7 279 This hole 6 ft long

Iron attacked showing pits

#8 8 292 This hole 4 ft 6 long

Small rust spots 1/16 in into the

line 10" pipe

81

6 ft joint exposed slight leak
cupped slightly, no deterioration, 10%
sandy clay loam

joint shown, slight leak, caused by
loam, 20% Depreciation

pipe about 1/2 covered with rust

This section in at crags so as to show
about 1/2 deep numerous small pit marks in Iron

completely covered with rust and
the Iron 50%
33%

small rust, slight rust pits in
lead started from joint 10%

rusted very much underneath
1/2 in deep 50%

pipe shows rust about 1/5 of surface
Iron 50%