

Walk Ave South from 25 St

No of Hole	Distance Paces	Remarks
#1 ^{1/2}	4	6" branch to depot, pipe at least 1/16 duct, 50% deterioration,

#13	2	121 This Hole 6 ft long at joint exp 3/16 out of line rust pipe Deterioration 20%
-----	---	---

#14	285	Pipe exposed length varying from the diam of a thick joint exposed lead started
-----	-----	---

#15	384	pipe exposed length of 4 varying from 3/4" to 1/4 in Diam
-----	-----	---

#16	487	joint-exposed lead pipe exposed for 6 ft - rust
-----	-----	---

#17	6	621 pipe exposed 5 ft pipe very very good
-----	---	---

Property line

33

shown for 3 ft, pipe badly fitted, soil loose clay.

joint-exposed pipe badly stepped shows on top of pipe a number of

of 4 ft dry sandy soil & rust to diam of 25 etc pipe 1/16 duct pipe good, joint caused by two slips, 10% ft dry sandy soil four rust spots 33 1/3 deterioration

started, and caused by two slips shows pipe in good condition 10%

soil gravelly and sand more pipe capped at joint 0%