

Lincoln Ave South from 25 St

No of Hole	Dist-Boxes	Remarks
1 #18	4	6" pipe 5 ft exposed Deterioration 30% soil
2 #19	123	6" pipe, 4 ft 6 exposed fully 1/16 in deep soil gravel
3 #20	285	6" pipe exposed for a streak of rust on bottom for places more than 1/16" deep
4 #21	384	6" pipe, exposed for 1/16 in deep 1/2" wide 2 1/2 in long the whole length exposed one rust spot
5 #22	487	6" pipe exposed for deep as large as a nickel exposed in good condition Did not corrod.
6 #23	621	

Property Line

34

rusty numerous pits, sandy gravel	
bitches on the badly rusted and clay and sand	50%
6 ft - rust spots over top the whole length 3" wide rust in	75%
6 ft - one rust spot on top pipe full numerous rust spots on bottom extending soil clay and gravel on bottom 1/4" wide 1 1/2" long strong 1/16 deep	75%
6 ft - very rusty rust placed 1/16" deep numerous pits 1/16 deep joint	50%
off all the rust soil clay gravel + sand	