

Oct 31st 1900

Twenty Third St. from Lincoln Ave Prop Lines

No. Hole	Dist. Faces	Remarks	
#49 West	1	on prop line 6 in pipe. Joint slight leak badly bent by calking 66%	4 or 5 badly pitted deeps - on both sides of joint - Soil adobe clay Punctured & pitted extensively
#50 West	2	78 6 in pipe - Connection to small - some very deep	158-73 rd Street much rust - many pits large and Soil medium dry adobe clay 75%
#51 East	1	on curb line 6" pipe at joint - Leaking Soil adobe very wet	Lead starting - badly pitted 50% perhaps more
#52 East	2	71 6 in pipe - Joint leaks - pipe in good condition	bad condition as rust around joint otherwise Soil clay and sand 40%

Twenty Fourth St. from Lincoln Ave Prop Lines

No. Hole	Dist. Faces	Remarks	
#53 West	1	135 6" pipe - badly pitted on Soil sandy clay dry	Bottom - quite numerous on top .66%
#54 East	1	154 6" pipe - good Soil loam dry	10%