

53

NOV - 1st 1900

44

Washington Ave. North from 25th St. prop lineNo. of hole Dist.
Paces#63 9 1419 12" Pipe - Good Condition
Soil Cam - damp

10%

#64 10 1632 12" Pipe - joints - slight leaks
Soil coarse sand dry
Washington Ave Notes N. from hole #10 continuedrust on under side but no pits
on page 65

10%

Twenty Fourth St. from Wash Ave prop lines

No. of hole Dist.
Paces#65 East 1 119 6" Pipe, two small deep -
Soil damp sandpits - and several smaller ones
and clay

25%

Twenty Third St. from Wash Ave prop lines

No. hole Dist.
Paces#66 East 1 86 6" Pipe - In good con-
dition - Soil wet clay

said to have been retared with 2 yrs

10%

#67 West 2 125 6" Pipe - In good con-
dition - Soil wet clay

diton -

10%

Twenty Second St. from Wash Ave prop. lines

No. hole Dist.
Paces#68 West 1 116 6 in pipe - good con-
dition - Soil Clay - dry

diton

10%

#69 East 2 96 6 in pipe. Practically
Soil wet claynew pipe - good condition
much water

10%