

#97 ✓

Adams Ave 130ft South of 25<sup>th</sup> St. 6"45  
pipe - good condition Soil Sand & gravel dry  
old wooden pipe also uncovered - found in  
good condition

#98 ✓

Adams Ave 230ft S of 25<sup>th</sup> St. 6" pipeSome rust and few pits Soil wet sand  
in fair condition 10%  
some rust around connection to #2529

#99 ✓

Adams Ave 180ft S of 23<sup>rd</sup> St. 6" pipeabout 10% depreciation  
considerable rust Soil sand dry

#100 ✓

Adams Ave 125ft N of 26<sup>th</sup> St. 6" pipe.at joint - slight leak - bent by racking. deeply  
pitted - 66% Soil wet sand

#101 ✓

Adams Ave 30ft N of 26<sup>th</sup> St. 6" pipe in

good condition - Soil dry sand

#102 ✓

26<sup>th</sup> St 320ft N of Adams St. 6" pipe in

good condition Soil Sand dry

#103 ✓

Adams Ave 100ft S of 26<sup>th</sup> St 6" pipe. Some

rust - Soil moist sand 10%

#104 ✓

Adams Ave 250ft S. of 26<sup>th</sup> St. 6" pipe atjoint slight leak, considerable rust <sup>60</sup>8 pits  
around joint - a few deep pits - 33%  
Soil gravel and sand