

#122 ✓  
Wash. Ave 300 ft S. of 31<sup>st</sup> St. 10" pipe - at connection to # 3156 - slightly pitted - badly rusted - Leak at joint or connection 30%  
Soil gravelly clay wet 48

#123 ✓  
Wash. Ave - At connection to Hydrant 32<sup>nd</sup> St 10" pipe - Leaking badly - bent where it has been caulked - much rust, numerous pits -  
Soil wet clay and loam 50%

#123 ✓  
35<sup>th</sup> St - on Wash. Ave  
Hydrant connection pipe 6" rusted - deep pits - Soil wet clay and loam 50%

#124 ✓  
Wash. Ave 355 ft S. of 32<sup>nd</sup> St. 10" pipe - slight rust no pits - Soil clay dry 10%

#125 ✓  
Wash. Ave 924 ft S. of 32<sup>nd</sup> St - 10" pipe - very little rust 10% Soil dry clay

#126 ✓  
Wash. Ave 30 ft N. of 35<sup>th</sup> St - 10" pipe some rust - pits just appearing  
Soil dry sand and gravel 10%

#127 ✓  
Wash. Ave 75 ft N. of 36<sup>th</sup> St - 10" pipe - some rust - pits just appearing - Soil dry clay 10%

#128 ✓  
35<sup>th</sup> St 315 ft E of Wash. Ave 4" pipe - much rust - many pits deep -  
Soil dry clay 50%

#129 ✓  
Wash. Ave 8 prop line of 34<sup>th</sup> St 10" pipe - very little rust - no visible pits -  
Soil gravelly clay dry 10%