

#148 ✓

Jefferson Ave 85 ft N of 25<sup>th</sup> St. 6" pipe

slight rust small pits - Soil dry sand

57  
15%

#149 ✓

Jefferson Ave 200 ft S of 24<sup>th</sup> St. 6" pipe at jointvery slight leakage - badly bent - considerable rust  
heavy pits - Soil loam dry

50%

#150 ✓

24<sup>th</sup> St - 750 E of Jefferson Ave. 6" pipe, verylittle rust, coating in good condition  
Soil dry sand

5%

#151 ✓

24<sup>th</sup> St. 360 N. of Jefferson Ave 6" pipe at jointconnection to #541 very much rust and deep  
pits shows water - water works man gone for  
tools to recant joint - Soil sandy gravel

90%

#152 ✓

Jefferson Ave 135 ft N of 24<sup>th</sup> St 6" pipe (selectedfor examination) badly rusted in pits -  
Soil dry sand

25%

#153 ✓

Jefferson Ave 145 ft S. of 23<sup>rd</sup> St. 6" pipe - much

rust, pits appearing - Soil dry sand + clay

25%

#154 ✓

23<sup>rd</sup> St. 215 ft E of Jefferson Ave 6" pipevery badly rusted and pitted  
Soil sandy clay moist.

50%

#155 ✓

23<sup>rd</sup> St - 90 ft N. of Jefferson Ave 6" piperust and pits just appearing  
Soil clay + sand dry

25%

#156 ✓

Jefferson Ave 200 ft N of 23<sup>rd</sup> 6" pipe - badlyrusts - some pits -  
Soil loam

33 1/3