

#157 ✓
Jefferson Ave 200 ft N. of 22nd St. 6" pipe

52
Connection to # 2150 badly rusted
around connection - and pitted
Soil damp loam 66%

#158 ✓
Jefferson Ave 125 ft S of 21st St. 6" pipe -

badly rusted and pitted - Soil damp loam 66%

#159 ✓
21st St. 225 ft E. of Jefferson Ave 6" pipe -

much water around pipe - rusted 70%
Soil very wet sand & clay

#160 ✓
Jefferson Ave 150 ft S of 27th St. 6" pipe much

rust, badly pitted
Soil loam 66%

now 21st ✓
#161 ✓
Jefferson Ave 125 ft N of 27th St. 6" pipe - at joint

wet sand - badly rusted - and very little
pitted 20%

#162 ✓
Jefferson Ave 20 ft N. of 21st St 6" pipe. Very

much rust and pits
wet alkali sand 66%

#163 ✓
" " 330 ft N of 21st St. 6" pipe - covered

with alkali - no rust - no pits
alkali sand dry 10%

#164 ✓
" " 100 ft S. of 20th St. 6" pipe - much

rust, badly pitted - covered with alkali
Soil alkali clay dry 66%

#165 ✓
20th St 60 ft E of Jefferson 6" pipe at con-

nection to cemetery - good condition
Soil sand dry 10%