

#166 ✓

20<sup>th</sup> St 150ft W of Madison

6" pipe - joint-

pipe covered with alkali - Rough exterior  
fairly good soil moist sand - some  
alkali 10%

53

164 ✓

Madison Ave 100ft S. of 20<sup>th</sup>

6" pipe - In

fair condition - no rust, no pits  
dry soil - loam 10%

168 ✓

20<sup>th</sup> St 100ft E of Madison

6" pipe - joint

and pipe in good condition  
soil sandy clay dry

169 ✓

20<sup>th</sup> St 150ft W. of Monroe

6" pipe - In

good condition  
soil dry sand + gravel

170 ✓

20<sup>th</sup> St 150ft E of Monroe

6" pipe - some

rust - slightly pitted  
soil dry sand and gravel 25%

171 ✓

Monroe Ave 150ft S. of 20<sup>th</sup> St.

6" pipe - joint-

badly rusted and pitted  
soil gravel + loam moist 60%

172 ✓

Monroe Ave 75ft N of 2<sup>nd</sup> St.

6" pipe -

some pits and rust  
moist loam 40%

173 ✓

Monroe Ave 200ft S of 2<sup>nd</sup> St. 6" pipe - somerust and slightly pitted  
wet sand 25%

174 ✓

Monroe Ave 150ft N of 2<sup>nd</sup> St. 6" pipe - somerust and pits  
wet sand + clay 50%