

#175 ✓

21st St. 200 ft E of Madison Ave. 6" pipe atconnections # 718 very badly rusted -
some pits - Road57
50%

176 ✓

Madison 150 ft N of 21st St. 6" pipe - somerust + slightly pitted
soil damp sand

174 ✓

21st 180 ft N of Madison 6" pipe - somerust - pits beginning to appear
soil wet loam

25%

178 ✓

Madison 150 ft S of 21st St. 6" pipe - somerust pits appearing
soil sandy clay moist

20%

179 ✓

Madison 100 ft N of 22nd St. 6" pipe. con-siderable rust. badly pitted
soil sandy clay moist

66%

180 ✓

22nd St 100 ft E of Madison 6" pipe. somerust one small pit
sandy clay

15%

181 ✓

22nd St 200 ft N of Madison 6" pipe. jointsleaking rust and badly pitted
Sandy clay

66%

182 ✓

Madison 60 ft S of 22nd St. 6" pipe. rustand pitted considerably
soil sandy clay

45%

183 ✓

" 100 ft N of 22nd St. 6" pipe slight

rust - no pits

dry clay

10%