

- 184 ✓
23rd St 140 ft E of Madison 6" pipe - rust and pits clay + sand 33% 55
- 185 ✓
23rd St 150 ft W of Madison 6" pipe - rusted & badly pitted in places sandy clay 33%
- 186 ✓
Madison 125 ft S of 23rd St 6" pipe and connection to # 2825 - very badly rusted and deeply pitted around connection. life of pipe nearly gone soil clay moist 90%
- 187 ✓
Madison 200 ft N of 24th St 6" pipe - good condition slight rust soil clay 5%
- 188 ✓
24th St 130 ft E of Madison 6" pipe - joint - leak slightly - one pit sandy clay 10%
- 189 ✓
Madison ave 400 ft S of 24th St. 6" pipe no g badly rusted - and pitted sandy clay moist 33%
- 190 ✓
Monroe 150 ft N of 25th St - 6" pipe and connection to # 2465 slight leakage - some rust and pits soil clay damp 20%
- 191 ✓
Monroe 100 ft S. of 24th St. 6" pipe and joint slight rust and some pits adobe clay - damp 75%
- 192 ✓
24th St 150 ft E of Monroe 6" pipe and connection to # 818 slight leakage some rust and two or three pits adobe clay damp 25%