

- | | | | | |
|--------|---|-------------------|--|-----------|
| #193 ✓ | 24 th St 100 ft W. of Monroe | 6" pipe - | In fair condition | 56
10% |
| 194 ✓ | Monroe 220 ft N. of 24 th St | 6" pipe and | connection to # 2357 - slight rust and 200 pits | 10% |
| 195 ✓ | " 80 ft S of 23 rd St. | 6" pipe and joint | one pit - otherwise joint & pipe in fair condition - | 15% |
| 196 ✓ | 23 rd St. 100 ft W of Monroe | 6" pipe - one | small pit otherwise in good condition | 10% |
| 197 ✓ | Monroe 100 ft N. of 23 rd St. | 6" pipe In | good condition | |
| 198 ✓ | Monroe 100 ft S. of 22 nd St - | 6" pipe - | rust and pits | 33% |
| 199 ✓ | 22 nd St 165 ft E of Monroe - | 6" pipe - | considerable rust and some pits | 33% |
| 200 ✓ | Laney 50 ft N of 22 nd | 12" pipe hole | filled with water | 33% |
| 201 ✓ | 21 st St 150 ft W of Laney - | 6" pipe - | two Saddles put on to prevent leakage | 73% |

adobe clay damp.

adobe clay wet

adobe clay damp

soil clay moist

clay wet

soil wet sand and clay

soil wet sand & clay

pipe - rusted and pitted
wet sand & clay

badly pitted
wet sand & clay