

#202 ✓

21st St. 300 ft W. of Quincy 6" pipe -one saddle put on to prevent leakage
many large deep pits
wet sand + clay57
75%

203 ✓

20th St 75 ft W of Quincy 6" pipe -numerous small pits
dry sand + gravel

33%

204 ✓

Quincy 250 ft S of 20th St. 12" pipe -In fair condition
Sandy loam dry

10%

206 ✓

Quincy 60 ft N of 21st St. 12" pipe atjoint badly pitted and large
wet sand + clay

60%

206 ✓

Quincy 200 ft S of 21st St - 12" pipeIn good condition (new joint) ground shows
recent excavation -
wet clay207 ✓
Quincy 125 ft N of 23rd St 12" pipe -indications of having been played in three
or four places some pits
wet sand

50%

208 ✓

23rd St 100 ft E of Quincy. 6" pipe -some pits - three deep pits
loam - damp

33%

209 ✓

23rd St 100 ft W. of Quincy 6" pipeIn fair condition
wet sandy loam

10%

210 ✓

Quincy 100 ft S of 23rd St. 12" pipe -slightly rusted
soil sandy clay moist

10%