

M 90-29-46

Fm 90-29-46.75

Dist to o.c.m. (34th i adams) = 1518.13

Dist to SA = 1593.70

SA D 0-00-10

08

R 180-00-06

4D D 179-04-29

25.5

R 359-04-22

M 179-04-17.5

SA D 90-05-44

41

R 270-05-38

4D D 269-10-04

58.5

R 89-09-53

M 179-04-17.5

Fm 179-04-17.5

Dist to SA = 1593.70

Dist to 4D = 1764.88

\bar{X} @ o.c.m. (34th i adams)

o.c.m.
32nd i adams

D 0-00-11

6.5

R 180-00-02

o.c.m.
36th i adams

D 179-56-18

12

R 359-56-06

M 179-56-5.5

o.c.m.

D 90-05-40

37.5

R 270-05-35

o.c.m.

D 270-01-51

44.5

R 90-01-38

M 179-56-07

Fm 179-56-06.25

Dist to o.c.m. 32nd i adams = 1518.14

Dist to o.c.m. 36th i adams = 1486.09