

Cont.		Brass Mon.		
W.M	$\pi @$	200 S. 1200 W.		
$\frac{12}{13}$	D	90° 05' 40"		38.5"
$\frac{13}{14}$	R	270° 05' 37"		
18C	D	271° 38' 24"		23.5"
	R	91° 38' 23"		
	M	181° 32' 45"		
	F.M	181° 32' 47"		

Dist to $\frac{12}{13}$ W.M. = 1175.06

Dist to 18C = 2072.18

$\pi @$ WM $\frac{12}{13}$

76	D	0° 00' 10"		09.5"
	R	180° 00' 09"		

Brass Mon
200 S. 1200 S.

D	179° 12' 28"		26.5"
R	359° 12' 25"		

M = 179° 12' 17"

7G	D	90° 05' 40"		38.5"
	R	270° 05' 37"		

Brass Mon
200 S. 1200 S.

D	269° 17' 53"		51.5"
R	89° 17' 50"		

M = 179° 12' 13"

F.M. = 179° 12' 15"

Dist to 76 = 1581.96

Dist to Brass Mon
200 S. 1200 W. = 1175.06

$\pi @$ FH

7I	D	0° 00' 10"		09"
	R	180° 00' 08"		

7G	D	181° 56' 09"		06.5"
	R	01° 56' 04"		

M = 181° 55' 57.5"

7I	D	90° 05' 40"		38"
	R	270° 05' 36"		

7G	D	272° 01' 35"		33.5
	R	92° 01' 32"		

M 181° 55' 55.5"

FM 181° 55' 56."