

Control work (Huntsville State Highway)

4/16/87

Slagows
Lewier

3cc cor. nail split
14/13
23/24 between wit. mon.
North R/w
Mon. 2668.64

South R/w
Mon.

Set hub
W-P #1

Tack for
1/4 cor 13
24 W-P #1
Set hub
W-P #2

Set hub
W-P #3 66-28-52 249.27

↑
angles were
doubted.

W-P #1 W-P #3
Set cor mon
13/18
24/19 297-01-55 855.23 Fly 1
Tie

W-P #1 W-P #2
Set hub 0-00-02 2908.65
W-P #4 155-02-41 1424.35
180-00-08
335-02-47

W-P #2 W-P #4
Set hub 0-00-15 1424.41
W-P #5 139-44-24 1174.04
180-00-20
319-44-29

W-P #4 W-P #5
Wit cor for 0-00-05 1174.01
18/17 187-31-12 1175.16
19/20 180-00-19
7-31-24

R/w mon.
no. side 0-15-13 543.08

Set hub 0-00-05
W-P #6 152-07-45 737.40
180-00-19
332-07-49