

T@ 26 D

26 C D 0° 00' 12" 01" ✓  
R 179° 59' 50"

26 E D 148° 15' 23" 12" ✓  
R 328° 15' 01"

M 148° 15' 11" ✓

26 C D 90° 05' 40" 27.5" ✓  
R 270° 05' 15"

26 E D 238° 20' 47" 39.5" ✓  
R 58° 20' 32"

M 144° 15' 12" ✓

F.M. 148° 15' 11.5" ✓

Dist to 26 C = 2644.60

Dist to 26 E = 2057.63

6-8-88

T@ 26 E

$\frac{26}{35} \frac{25}{36}$  D 0° 00' 13" 08" ✓  
R 180° 00' 03"

26 D D 187° 57' 48" 39.5" ✓  
R 7° 57' 31"

M 187° 57' 31.5" ✓

$\frac{26}{35} \frac{25}{36}$  D 90° 05' 39" 33" ✓  
R 270° 05' 27"

26 D D 278° 03' 12" 02.5" ✓  
R 98° 02' 53"

M 187° 57' 29.5" ✓

F.M. 187° 57' 30.5" ✓

Dist to 26 D = 2057.62 ✓

1 Dist to  $\frac{26}{35} \frac{25}{36}$  = 493.08

T@  $\frac{26}{35} \frac{25}{36}$  Brass

Dist. to 26 E = 493.03

Dist. to 26 A = 424.08

Dist. to 35/36 = 2623.57

Dist. to 26 A = 4125.72

(148-15-11.50) xx

(187-57-30.50) xx