


Sec. 6

7-3-84

Hillier, Holmes, Barter

Fly Tie



Oak
Brush

3431
16
B.L.M.



HILL

CA
(Pike)

B.S. 68 (stream)

① = 188° 01' 40"

194.18'

5-31-89 D. Bytters
R. Balken

B.L.M. 3" Brass cap

1966 with Stone notches buried next to it.

Triangulation Pt.
NORTH

Scrub oak

58.15
Nail in
Tree

Fence
Post

5.50

Fence
Post

6.27

chokecherry Bush

Fence Post
Nail was lost
8.73

36	31
1	6
T. 7 N	
R. 7 E	