

(60)

was discovered in numbering from Sta 37 to 36 in which 35 was left out making 100 FT of an error in the cubic yard estimates. also an error was discovered in numbering from 40 to 42 in which 41 was left out but was also left out in the cubic yard estimates. All of which occurred on the 6th Division.

D. Jenkins Engineer
Washington Jenkins Assn

Sta 21+70 to 23+70 7th Division Barton's numbering and contracted by John Hudson see cross section ^{and} cu yd Books for estimates ^{of this strip}

Sta 22+70 to 23+60 Barton's numbering contracted by Joseph Hudson (see notes on estimates as above referred)

8 ft by yet taken out of sta 24 for 150 ft - 6 in
7th Division = 29.6 cu yds

Sta 23+60 to 26 Barton's numbering contracted by Wm Hudson see above - for estimates

26 to 28 (Barton's numbering) contracted by John H. Sill see above