

Survey made for Henderson
in S. W 1/4 Sec. 7. T. 5. N. - R. 1. W. and S. E 1/4 Sec. 1
T. 5. N. R. 2. W.

Quarry Cor. B
T. 5. N. R.

July 28th 11

Co. Mont 56.

587°-10'-30" E (old course)

center Co. P

507.9 Ft
526°-04' W

River
Ditch

381.70
222.42 Ft
291.06

587°-00' E
97.02

170 Ft
581°-00' W

68.64 Ft

See book "G" field notes
page 188.
of Co. Road Transit notes
Book C. page 70.

Ties to Mont N^o 56. July-1893
S. E 86:75 tel. pole
87.8 " "
71.7 Cor. post. Russell fence
one .4 below surface.
19204' E. Obsty. Pk.

See also. Book I. field notes
page 81. "G" 100-118-126-
L-Pages-3-195. J-106

Plat Book page
123-

T. 5. N. R. 2. W.
T. 5. N. - R. 1. W.

I-413, Wm Gill to Thomas Joyce. Sep 18-1874.
220. P. 1/4 E 1/4 Sec. 24, T. 6. N. R. 2. W. Beg. 27.82 ch. N. of
S. E. cor. of surz 1/4 Sec. - 7116 1/2 E 12.75 chs. 766 1/2 N
3.90 chs, 714° E 3.09 chs, to mid. Str. 789 1/2 W
66 chs, 516.80 chs, N 7.46 chs. to Cray. 15.44