

April 23-1919 - Levels on ³ is bottom of Lynner ditch
from Division point in above field N.W.

Taken just 1 day after the Co. cleaned out the ditch

B.M.		4294.501
	+ 0.65	4295.15
B.M.	- 4.185	4290.965
	+ 3.93	4294.79
0+0	3.55	4291.24
0+0	4.28	4290.51
0+9	4.35	4290.44
+ 17	4.30	4290.47
+ 51	7.45	4290.34
+ 75	4.65	4290.14
1+0	4.58	4290.21
+ 50	4.75	4290.04
2	4.87	4289.92
+ 50	4.95	4289.84
3	5.05	4289.74
+ 0.5	4.95	4289.84

on top Fred Johnson Iron fence post
H.I.
on stake to surface 6' N. of Mend Johnson Bridge ⁴⁺⁵⁰
H.I.
floor of concrete
bottom floor (concrete)
Mend bridge
bottom of ditch
on X piece - sill of gate across ditch inverted
on stake to surface N. of bridge
H.I.

B.M.		4290.965
	+ 3.80	4294.765
+ 50	5.03	4289.73
+ 67	4.73	4290.03
+ 82	4.66	4290.10
+ 91	5.05	4289.71
4	5.10	4289.66
+ 30	5.03	4289.73
+ 36	4.84	4289.92
	4.77	4289.99
+ 50	5.28	4289.48
5	5.38	4289.38
+ 50	5.21	4289.55
6	5.51	4289.24

bottom of S. and Wagon bridge in 4th Str
N
" ditch turns west
" ditch turns N.
" on top sill across ditch
" top junction cross piece

B.M.		4290.965
	+ 4.94	4295.905
6+50	6.58	4289.32
+ 59	6.51	4289.39
+ 67	6.25	4289.65
7	6.90	4289.00
+ 50	6.91	4289.99
+ 54	6.90	4289.00
B.M.	- 3.965	4291.940
	+ 2.650	4294.590
+ 66	5.05	4289.54
8	5.53	4289.06
+ 50	5.66	4288.93
9	5.60	4288.99
+ 50	5.76	4288.83
10	5.76	4288.83
+ 50	6.02	4288.57
11	5.96 = 5.96	4288.63
	- 5.05	4289.540
	+ 4.23	4293.820
+ 60	5.36	4288.46
+ 50	5.30	4288.52
12	5.57	4288.25
+ 0.6	5.45	4288.37
+ 0.6	5.14	4288.68
	- 1.210	4289.610

H.I.
on Patterson X piece
on bottom S. and Johnson bridge
bottom at regular gate
on X on top of X piece same
H.I.
bottom S. and Johnson bridge
opp. Cur. post Taylor bridge
bottom of canal
on top Taylor X piece - Head Gate
on April 21 '19 of 1st post 6' of Jack N.W. Cur

m.