

	Q	R	LT	T ₀	LT
25+00	4.78 C=4.52	2.39 5.12	7.13 7.13	7 ₀ F=0.22	56 C=38
26+00	6.76 C=5.59	4.67 C=4.19	8.91		F=0.65 F=0.05
27+00	9.02 C=2.09	7.20 C=2.64	11.31		F=2.07 F=1.57
28+00	5.44 L=2.97 C=.96	3.47 C=3.57 C=1.56	6.95	F=2.0 F=2.51	C=0.10 F=1.91
29+00	6.90 C=.63	5.07 C=1.23	8.14		F=2.44 F=1.84
30+00	8.47 C=1.48	6.70 C=2.08	9.74		F=1.56 F=0.96
31+00	5.96 C=2.99	2.08 C=3.59	5.19		F=0.1 C=0.5
32+00	6.93 C=3.66	5.14 C=4.26	8.13		C=0.67 C=1.77
33+00	11.07 C=0.37	C=0.97	11.38		