

12-9-75

## East Highland Estates #2

South End of roadway is very soft - from no compaction of Smedley installed water lines to four lots and also the installation of the two required sumps - Will want to check again before asphalt is laid next summer

Note: Was out here yesterday and explained that this area should be compacted.