

E_{rod}
Reading
0

OFF
SET
HUB

13.00	5.30	6.67	1.37	F=.11	F=1.48
14.00	4.86	6.95	2.09	F=.08	F=2.17
15.00	5.08	5.34	-.26	C=.04	F=.22
16.00	5.01	-5.25	-.24	C=.24	00
17.00	5.18	-5.68	-.50	C=.60	C=D.1
18.00	5.20	-5.74	-.54	C=.56	C=0.02
19.00	5.53	5.68	-.15	C=.70 38	C=.55
20.00	4.32	4.46	-.14	C=.08	F=0.06 F=0.1
21.00	5.52	5.80	-.28	C=.34 F=.34 06	F=.62
22.00	4.44	4.44	-	C=.15	C=.15
23.00	6.23	6.26	.03	C=.09	C=00 C=0.06
24.00	4.34	4.64	-.30	C=.42	C=0.12 C=0.1