

25+00	5.60	5.50	+ ¹⁰ 10	$C = \frac{24}{31}$	$C = \frac{.34}{.3}$
26+00	4.48	4.67	- ²⁰ 19 ₂₇	$C = .26$	$C = \frac{0.00}{0.1}$
27+00	5.53	5.50	+ 0.03	$C = \frac{24}{31}$	$C = 0.4$
28+00	4.78	4.39	+ 39	$C = .20$	$C = 6.0$
29+00	6.46	6.31	+ ²¹ 15 ₇	$F = .21$	$F = 0.07$
30+00	4.77	4.60	+ 17	$F = .17$	$F = \frac{.84}{3.8}$
31+00	5.97	6.12	- ¹⁵ 15 ₀	$F = .03$	$F = 2.0$
32+00	4.82	5.38	- .56	$F = .06$	$F = 6$
33+00	5.11	5.45	- ^{1.2} .34	$C = \frac{7}{34}$	$C = .48$
34+00	6.02	8.08	2.06 _{2.2} 1.84	$C = .22$	$F = 1.84$
35+00	10.06	10.24	.18	$C = 1.0$	
36+00	10.06	10.24	- .18	$F = .76$	$F = 9.4$
37+00	3.76	4.06	.30	$F = .81$	$F = 1.1$