

Q of Set

38+00 5.77 5.96 - + .19 F=.22 F=.41

39+00 4.75 5.06 .31 C=.36 00

40+00 5.55 5.83 .28 C=.03 F=.25

41+00 4.56 4.90 - .34 F=.52 ~~C=.8~~
⁵
18 ^{F=.86}

42+00 5.34 5.39 - .05 F=.73 F=.78

43+00 3.22 3.39 - .17 F=.16 F=.33

44+00 4.87 4.60 + .27 F=.56 F=.29
~~.83~~

45+00 3.40 3.84 - .44 F=.35 F=.79
³
⁵
²

46+00 E=.06