

	R-	U.T	F _s	G _L	G _R
4+50			5.27	103.85	99.8
5+00			5.24	103.82	99.98
5+50			5.15	103.97	100.16
6+00			4.91	104.21	100.34
6+25.6					
HUB			4.05	105.07	100.52
FE			8.61	100.51	100.52
T.P.			4.29	104.83	
	6.57	111.4			
6+00					
HUB			7.79	103.61	100.69
FE			10.71	100.69	100.69
0+50			7.35	104.05	100.90
1+00			7.24	104.16	101.11
1+50			6.95	104.45	101.32