

			F.S.		
49+00			3.25	4268.20	
			<del>1.15</del> 6.75		
50+00			6.20	4265.25	
51+00			5.46	4265.99	
46+00	4.20	4274.12		4269.92	
<del>177 SIDE</del> 46+00			9.80	4264.32	C=1.0
47+00			9.80	4264.32	C=.10
48			10.05	4264.07	F=0.1
49			9.40	4264.72	C=0.5
50			6.80	4267.32	C=3.1
51			8.50	4265.62	C=1.4
52			9.90	4264.22	0.00