

#2 - Recheck on Excavations on  
Bybee Dr. & East Highlands #4 if  
need be go back to mtw Shul  
on #4 @ 6175 & 21256.

#3. Randall Sub:

- a. 4 Fire Hydr in place
- b. no Red, Stop or Speed Signs
- c. no Monuments
- d. no Grates on Sumps at 2250w
- e. Better Backhoe on Lot #5 - full  
lot on south side of 2500N.
- f. Sewer Botes are low need  
to be raised.
- g. Patch work in roads.
- h. no Sump Jurns around on  
2250w.
- i. Street is not rolled to great.
- g. Overall job "fair"