

4 hrs.

① Made complete inspection of Wallace Christofferson Sub & Mr Christofferson's Sub does not meet in my opinion stds for these lots

6 1/2 hrs.

② Inspected Road on Hegevig Sub to see if Tife had made a cleanup on shoulders

③ Spent remainder of day in office on inspection of this & going over plans w/ Steel & signing for 5700 S. & 5675 S.