

MC-52

T. T. N. R. Z. W.  
May 24 '82

$\pi$  @ Rebar #1 on hill

B.S. Center<sup>4</sup> Rebar on Fence line (sec. 13.)

Hor  $\&$  Rt. To Rebar #2 on hill

197° 25' 00" ( 34° 49' 59" ) Down.

Hor Dist. #1 To Center Rebar

1455.81 Corrected Dist.

Vert  $\&$  4° 33'

Hor Dist. To Rebar in Fence line

East 430.14'

Vert  $\&$  5° 22'

Hor  $\&$  RT. 324° 24' 00"

#1 To #2

Hor. Dist. 905.69' CORR.

Vert  $\&$  1° 08'

$\pi$  @ Rebar #2

Hor. Dist. To E.  $\frac{1}{4}$  COR #215

VERT.  $\&$  12° 37' ?

F.S. Hor.  $\&$  (223° 11' 00") B.S. #1

→ 307.63' CORR. ← Double checked

$\pi$  @ #2 B.S. #1

F.S. To W.C. @ E.  $\frac{1}{4}$  COR.

Hor  $\&$  206° 18' 00"

Hor. Dist. (Corrected) 419.06'

Vert  $\&$  10° 23'