

3-14-83
(old)

T.6N. R.2W.

Hillier
Holmes

Township Section Control

✓ # 8
 179° 59' 25" π @ N 1/4 cor. sec. 34
 359° 59' 25" B.S. N.W. cor. sec. 34
 180° 00' 02" F.S. N.E. cor. sec. 34
 359° 59' 24"
 179° 59' 23"
 180° 00' 02"

179° 59' 25"
 25
 24-5 26
 23

✓ # 9
 180° 02' 11" π @ S 1/4 cor. sec. 35
 00° 02' 14" B.S. S.W. cor. sec. 35
 179° 59' 58" F.S. S.E. cor. sec. 35
 00° 02' 13"
 180° 02' 12"

180° 02' 12.5"

10 ✓
 178° 22' 51" π @ S.E. cor. sec. 35
 358° 22' 51" B.S. S 1/4 cor. sec. 35
 180° 00' 00" F.S. S 1/4 cor. sec. 30
 358° 22' 54"
 178° 22' 53"
 359° 59' 58"

53.5
 51
 52
 52
 178° 22' 52"

✓ # 1
 3-16-83 T.5N. R.2W.
 89° 51' 58" π @ E 1/4 cor. sec. 3
 269° 51' 53" B.S. N.E. cor. sec. 3
 179° 59' 57" F.S. Center of sec. 3
 269° 51' 56"
 89° 51' 59"
 00° 00' 02"

✓ # 2
 180° 00' 55" π @ Center of sec. 3
 00° 01' 00" B.S. E 1/4 cor. sec. 3
 179° 59' 56" F.S. W 1/4 cor. sec. 3
 00° 01' 01"
 180° 00' 56"
 179° 59' 58"