

Enter M. hole Cor. 25 +
Lincoln, Good condition
Tile dry.
Water 1" deep.
Light $\frac{1}{2}$ B. east invisible

Enter M hole Lincoln Belt 24 +
25, Good condition,
Water $\frac{3}{4}$ " deep. ^{nearly} stagnant
Tile dry.
Light $\frac{1}{2}$ B. south
invisible.

Enter M hole 25 ~~Bit~~
Lincoln + wall.
Good condition. + dry
Water 2 $\frac{1}{2}$ " deep.
Tile dry
Light $\frac{1}{2}$ B. east visible