

Drain Inspection

April 18 - 7 1/2" 30" Sizer (Campbell Inspector)
 Begin at 27th & Hall man hole.
 Leaks on the E. side just above the source 15 or
 20 from man hole, been stopped but started in
 a new place. Leaks are size of straw.
 1st for 1/2. N. one leaks quite a little
 E. " Still leaking.
 2d " 1/2. Streams 1/2 as thick as your finger
 Leak in bottom 5 or 10' N of 2nd for 1/2 -
 Also little leak on E. side about 12'
 north of 2d for 1/2
 3d for 1/2. E. one leaking around "4"
 N. one "OK"
 4th for. In fair shape.
 5th " OK.
 6th " Running small stream on West.
 7th " East one still running small stream.
 8th " N. one leaking quite badly.
 9th " OK
 10th " Still leaking badly.
 11th " OK
 12th " OK
 13th " OK

Man hole bet 26 + 27 on Hall on
 Well plastered. Just deeping on from blind end.
 Tile from South running 1/2 full. 2" Water in tile.
 1st for 1/2. OK.
 2d " " " "
 3d " " West one leaking some.
 4th " " OK.
 5th " " OK
 6th " " OK
 7th " " OK
 8th " " OK
 9th " " OK
 10th " " OK
 11th " " OK
 About 5' N of 11th for 1/2 on N. Side don't
 leak 1/2 size of finger.
 12th for 1/2 OK.
 13th " " OK.
 14th " " OK.