

Oct. 6 - p.m.

Survey to check proposed plat
of Capitol Hill Adot.

Began by finding $\frac{1}{4}$ P. post between
Secs. 33 & 34 - 6ⁿ - 1^w. Found fence
posts standing by the side of the
short cedar stake 3" diam. with the
bark on. I remove fence post
and set transit about the hole
till the angle between Eyrick Peak
and Court House Spire was from
the mean of six readings $71^{\circ} 20'$
which was the best I could do without
moving transit off from the post hole.
N.B. Jenkins in notes of locations of
Section corners in 1888 gives the
above angle $71^{\circ} 19\frac{1}{2}'$ which reading
I was endeavoring to check with.
Taking therefore the setting which
gives the above angle $71^{\circ} 20'$ as
as near the original point as I
can obtain I perform the