

Continued

Dist	Slope	Inclination		Category			
		Road	Survey				
200.000	-0°29	104°	104°	100	-.008 +.047	+0.031	200.031
200.000	-0°55	95°	97°		-.010 +.026	+0.014	200.014
200.000	-0°43	92°	93°	100	-.016 +.034	+0.008	200.008
200.050	-0°25	94°	93°		-.010 +.006	+0.028	200.078
<u>842.050</u>						+0.081	<u>800.131</u>
200.000	-0°20	90°	92°	100	-.004 +.033	+0.019	200.019
200	0.11	94°	95°	100	-.010 +.007	+0.016	200.016
200	0°26	92°	92°	100	-.020 +.006	+0.017	200.017
40.	0°00		92°		-.010 +.006	-0.004	39.996
196.49	0°14	92°	92°	100	-.002 +.031	+0.009	196.499
836.49				100	-.020	+0.057	<u>836.547</u>

B43

78

B43

{ To Hub about 70' South
of Center 25th bearing by cut
(2045)

{ To Monument Cor. Hinson
+ 24th 56