

Oct 31st 1900Lincoln Ave North from 21st St Property line

No. Hole

Dist
Paces

Remarks

43

9

875

6 in pipe - Connection at 2138
at connection but no pitsLincoln considerable rust caused from leakage
otherwise pipe in good condition
Soil - sandy gravel 18%

? 9 1/2

Too much water

Twenty First St. from Lincoln Ave property line

No. Hole

Dist
Paces

44

Ch of Lincoln

1

9 from N prop line of 21st St.

No examination on account of water

45

West

2

98

6 in pipe in good

condition - soil sand

10%

46

East

1

120

6 in pipe two connections
soil clay - badly pittedone South - 247-21st St - and one North - 246-21st St -
33%

Twenty Second St. from Lincoln Ave prop line

No. Hole

Dist
Paces

47

West

1

79

6 in pipe joint - pipe

in good condition - soil fine dry sand

10%

48

East

1

69

6 in pipe - one pit 1/2 sq
soil sand.

in area otherwise pipe in good condition

25%