



Figures in red - correction for error in tape  
 error = .048 % on North side  
 all figures except black & void  
 25th STREET

- #1 = 93+56.6 W. end of basement ventilator 2.5 wide 3.0 Long
- #2 = 93+67.4 " " " " " 2.5 " 3.0 "
- #3 = 94+00.8 " " " " " 2.0 " 3.0 "
- #4 = 94+10.6 " " " " " 2.0 " 3.0 "
- #5 = 94+16.8 " " " side walk +2 wide 19.2 Long about 6% along curb  
 2' below curb grade
- #6 = 94+69.8 " " " basement ventilator 2.3 wide 3.0 long
- #7 Note - This mark in fair condition with exception of 3 small holes about  
 1x1. 2 or 3 inches deep