

+80 3 R

+73 0

+60 5 L

+40 10 L

+20 8 L

+11 0

Sta 4 S.

$318^{\circ} = \text{Sta 4 S } 6 \text{ R Def. } 13^{\circ} 54' \text{ R}$

300 12 R

280 6 R

260 2 R

253 0

240 1 L

220 2 L

200 2 L

190 0

180 3 R

160 7 R

140 12 R

120 8 R

A. F. PARKER