Boundary Line Agreement

CALC SECTION CORNER

FND STREET MONUMENT

FND REBAR AND CAP


SET #5x24" RFBAR AND

CAP STAMPED LANDMARK

ROAD/STREET DEDICATION

FND CURB NAIL

PART OF THE SW 1/4 OF SECTION 06 & THE NW 1/4 OF SECTION 07, TOWNSHIP 7 NORTH, RANGE 1 EAST, SALT LAKE BASE & MERIDIAN UNINCORPORATED WEBER COUNTY, UTAH - Date of Survey: May 2018



NARRATIVE

- 1. The purpose of the survey is to identify common dividing lines and reconfigure the parcels shown. This project began as a subdivision plat but due to time constraints it has been decided that a boundary line agreement would facilitate the immediate needs and the subdivision could be pursued at a later date.
- 2. The basis of bearing is shown on the plat and in the boundary description.
- 3. The Don Shaw Subdivision No.1 was surveyed by Great Basin Engineering and recorded Sept. 11, 1987. The plat is recorded as Plat book 29 page 71. GBE notes the basis of bearing for their plat to be between the NW corner of Section 7 which was a brass cap and the S 1/4 corner which was also a brass cap but broken and disturbed.
- 4. The current monument location was not used for the GBE subdivision. In 1987, according to county records, the S 1/4 corner was at a position 34.2 feet south of the current brass cap. The Don Shaw Subdivision no.1 was retraced with the best available evidence, that being the Northwest corner of Section 7, a found rebar identified by the land owners as the original survey marker, and existing fencing.
- 5. The retracement of the subdivision identified a location for the S 1/4 corner where it was when GBE did the survey and produced a position that is 33.56 feet southerly of the existing monument.
- 6. The identification of the historic, 1967, section line was made by use of the evidence of the Don Shaw subdivision as noted in paragraph 4. The plat identifies this section line with a distance of 2395.18 feet. The two section lines are shown on the plat.
- 7. 5950 North Street right of way has been established by the Weber County Surveyor in May of 2019. Their determination of this right of way was made by rotating a County road deed, Book 819 page 137, so that the call of North matches the monumented section line.
- 8. Road establishment for both 5950 North Street and North Fork Road
- a. The location of the roads are not straight forward. There is an unrecorded subdivision titled North Fork Park-Kammeyer Addition in he County Planning records that show the location of 5950 North Street as being a 50 foot right of way width. Platting the location of the subdivision and identifying the existing road by fencing and edge of oil show that the current occupied location of the road is not in the same place as identified by that plat if the south boundary of the Kammeyer plat is assumed to be coincident with the south section line of Section 6.
- b. There is also a deed from Kammeyers to Weber County Corporation B819 p137 that granted the title to 5950 North Street as it is shown on the Kammeyer plat which is evident from the writing of the description and the plat drafting
- c. Making the assumption that Weber County Surveyor has done by rotating the county deed places the existing pavement in the center of the described right of way. However, the location does not conform to the Kammeyer plat as intended.
- d. Because the county deed was written as part of the project for the Kammeyer plat it would follow that the Kammeyer plat also needs rotation of the same amount. In doing so the south boundary of the plat no longer matches the monumented section line. The county tie sheet records provide information related to the county monument history. e. From an examination of the Kammeyer plat it can be surmised that the Southwest corner of Section 6 was considered to
- be a fence corner (this is documented on the county tie sheets and indicated that a brass cap was set by the post). The south 1/4 corner was not called out on the plat, however, the south boundary of the plat was labeled as such.
- f. The south 1/4 corner was established as a county brass cap in 1967, so the monument would have been in place when the Kammeyer plat was produced.
- g. It appears that the property description for the Nicosia's originated as Lot 3 of the Kammeyer unrecorded subdivision. By holding the rotated Lot line between Lots 2 and 3 of the Kammeyer unrecorded subdivision as the boundary between the parcels. In doing so this does not create a conflict with the metes descriptions of the Nicosia property since it too would be rotated similarly.
- h. 5950 North Street has been identified by a Great Basin Engineering survey filed as ROS 4839 done in 2013 which identified the property line of the LDS Church camp as being very close to the existing fence that is on the northerly side of 5950 North Street. When offsetting this north right of way line fence a distance of 60 feet to the south the line conforms quite closely to another piece of fence line that exists on the south side of the street. However, because the county was only deeded a 50 foot right of way for this street I believe it proper to hold the width of 50 feet.
- i. The Don Shaw Subdivision identified the location of North Fork Rd as being a split of existing fences and holding the southwesterly fence as the right of way for said subdivision. From our measurements the distance between the fence on the northeasterly side of North Fork Road and the Don Shaw Subdivision boundary are quite close to a 66 foot distance. j. Using Don Shaw Subdivision location for the right of way and offsetting the 33 feet for the center of North Fork Road produces a location for the center of the road as shown hereon.
- k. For this plat I am holding the Don Shaw Subdivision right of way location to the point where it intersects with the established location of 5950 North Street and then establishing a rounded corner for future road expansion.
- 9. The Nicossia parcel was surveyed by Landmark in 1997 indicating that the Northeast corner of the parcel was a found T-post. At this location we found a rebar and cap set by Landmark still in place. This location was not used for the right of way of 5950 North Street by the county which places the county determined right of way to be north of the rebar and cap.
- 10. Documents used or reviewed in this survey are, but not limited to, the following:
- a. Unrecorded Subdivision plat titled north Fork Park-Kammeer Addition, Drawn by E. Paul Gilgen, held in the county planning office.
- b. Current Tax Maps.
- c. Deeds, Book-Page; 750-688, 819-137, Entry# 879209, 927713, 958077, 958077, 1020941, 1114677, 1118264, 1508117, 1519632, 1667648, 1667649, 1848425, 2039639, 2358437
- d. Records of Survey; 1812, 2737, 3794, 4217, 4839
- e. Subdivision plats; Don Shaw Subdivision No.1, Nicholls Subdivision.

SURVEYOR'S CERTIFICATE

3-22-ZOZZZ

I, Ernest D. Rowley, do hereby certify that I am a

professional land surveyor in the State of Utah and hold license no. 171781-2201 in accordance with Title 58,

Chapter 22 known as the Professional Engineers and Professional Land Surveyor's Licensing Act, have made a

survey of the property(s) shown hereon in accordance

prepared from the field notes of this survey and from

placing monuments as represented. That this plat was

documents and records as noted hereon. I further certify

that, to the best of my knowledge and belief, all lots mee the current requirements of the Land Use Ordinance of

with UCA 17-23-17, verifying measurements, and

This Plat is the Intellectual Property of Landmark Surveying, Inc., all legal rights are reserved.

| Landmark Surveying, 9uc. A Complete Land Surveying Service www.LandmarkSurveyUtah.com | 4646 South 3500 West - #A-3 West Haven, UT 84401 801-731-4075 | |
|--|---|----------|
| DEVELOPER: Craig and Lynette C Address: 5931 North Northfork Road, Liberty, UT 84310 | berg | 1 of 1 |
| SW 1/4 of Section 06, Township 7 North, Range 1 East, & NW 1/4 of Section 07, Township 7 North, Range 1 East, Salt Lake Base and Meridian. | Record or | f Survey |
| Revisions | DRAWN BY: | EDR |
| | CHECKED BY: | |
| | DATE: | |

FILE: 3670