

12-9-83

(18)

Sec. 26



T.6N. R.2W.

T. @ R.R. spike B.S. $\frac{26}{35}$

FLY TIE to (26)

92° 51' 13"

8.30' West to (26)



2-01-84

Weber Co.
1963

(26)

Note: Had to move
because of power pole on
South R/W