

X @ 30/31
1/6

31C	D	2000	10	570	19
	R	18000	29		
BFE	D	8043	52		09
	R	2644	16		
	M =	8043	45		
31C	D	9005	42		56
	R	27006	10		
BFE	D	17049	19		34
	R	35049	50		
	FM =	8043	38		

Dist to 3K = 2715.71

Dist to BFE = 2455.80

~~12-13-84 B. B. ... T. Wood~~

X @ 30/29

29A	D	000	12		23.5
	R	19000	35		
30A	D	12822	40		49
	R	30822	58		
	M =	12822	26		
29A	D	9005	41		52.5
	R	27006	04		
30A	D	91828	04		14.5
	R	3828	25		
	M =	12822	22		

FM =

Dist to 29A = 4328.82

Dist to 30A = 1341.36